

## DEVILBISS TANK / BINKS TANK CROSSOVER CHART

**PART NO.**

<b>2 Gallon</b>	<b>Replacement</b>	<b>Description for Binks Replacement in Stainless Steel</b>
QMST-5200	83S-200	The Direct replacement has a single regulator, and is branded Binks.
QMST-5210	83S-210	The Direct replacement is branded Binks. There are no other differences.
QMST-5212	83S-211	The Similar replacement has a direct drive agitator, and is branded Binks
QMST-5211	83S-211	The Direct replacement is branded Binks. There are no other differences.
QMST-5213	83S-213	The Direct replacement is branded Binks. There are no other differences.
QMST-5216	83S-226	The Similar replacement has two regulators, and is branded Binks
QMST-5220	83S-220	The Direct replacement is branded Binks. There are no other differences.
QMST-5221	83S-221	The Direct replacement is branded Binks. There are no other differences.
QMST-5223	83S-223	The Direct replacement is branded Binks. There are no other differences.
QMST-5226	83S-226	The Direct replacement is branded Binks. There are no other differences.
QMST-5230	83S-220	The regulators on the Similar replacement have a lesser turndown ratio. These are also branded Binks.
QMST-5231	83S-221	The regulators on the Similar replacement have a lesser turndown ratio. These are also branded Binks.
<b>5 Gallon</b>		
QMST-5500	83S-500	The Direct replacement is branded Binks. There are no other differences.
QMST-5502	83S-513	The Similar replacement has a air driven/gear reduced agitator and is branded Binks.
QMST-5510	83S-510	The Direct replacement is branded Binks. There are no other differences.
QMST-5512	83S-513	The Similar replacement has a air driven/gear reduced agitator and is branded Binks.
QMST-5513	83S-513	The Direct replacement is branded Binks. There are no other differences.
QMST-5516	83S-516	The Direct replacement is branded Binks. There are no other differences.
QMST-5520	83S-520	The Direct replacement is branded Binks. There are no other differences.
QMST-5523	83S-523	The Direct replacement is branded Binks. There are no other differences.
QMST-5526	83S-526	The Direct replacement is branded Binks. There are no other differences.
QMST-5533	83S-533	The Direct replacement is branded Binks. There are no other differences.
<b>10 Gallon</b>		
QMST-51000	83S-1013	The Similar replacement has a single regulator, and is branded Binks.
QMST-51002	83S-1013	The Similar replacement has a single regulator, and an air driven/gear reduced agitator and is branded Binks.
QMST-51010	83S-1010	The Direct replacement is branded Binks. There are no other differences.
QMST-51012	83S-1013	The Similar replacement has a air driven/gear reduced agitator and is branded Binks.
QMST-51013	83S-1013	The Direct replacement is branded Binks. There are no other differences.
QMST-51016	83S-1016	The Direct replacement is branded Binks. There are no other differences.
QMST-51020	83S-1020	The Direct replacement is branded Binks. There are no other differences.
QMST-51023	83S-1023	The Direct replacement is branded Binks. There are no other differences.
QMST-51026	83S-1026	The Direct replacement is branded Binks. There are no other differences.
QMST-51033	83S-1023	The regulators on the Similar replacement have a lesser turndown ratio. These are also branded Binks.
<b>15 Gallon</b>		
QMST-51500	83S-1510	The Similar replacement has a single regulator and is branded Binks.
QMST-51510	83S-1510	The Direct replacement is branded Binks. There are no other differences.
QMST-51512	83S-1513	The Similar replacement has a air driven/gear reduced agitator and is branded Binks.
QMST-51513	83S-1513	The Direct replacement is branded Binks. There are no other differences.
QMST-51520	83S-1520	The Direct replacement is branded Binks. There are no other differences.
QMST-51523	83S-1523	The Direct replacement is branded Binks. There are no other differences.
QMST-51530	83S-1520	The regulators on the Similar replacement have a lesser turndown ratio. These are also branded Binks.
QMST-51533	83S-1523	The regulators on the Similar replacement have a lesser turndown ratio. These are also branded Binks.

*(Continued on next page)*

## DEVILBISS TANK / BINKS TANK CROSSOVER CHART

**PART NO.**

<b>2 Gallon</b>	<b>Replacement</b>	<b>Description for Binks Replacement in Galvanized Steel</b>
QMGT-5200	83G-210	The Similar replacement has a single regulator, and is branded Binks.
QMGT-5201	83G-211	The Similar replacement has a single regulator, and is branded Binks.
QMGT-5210	83G-210	The Direct replacement is branded Binks. There are no other differences.
QMGT-5211	83G-211	The Direct replacement is branded Binks. There are no other differences.
QMGT-5213	83G-213	The Direct replacement is branded Binks. There are no other differences.
QMGT-5220	83G-220	The Direct replacement is branded Binks. There are no other differences.
QMGT-5221	83G-221	The Direct replacement is branded Binks. There are no other differences.
QMGT-5223	83G-221	The Similar replacement has a direct drive agitator
QMGT-5226	83S-526	The Similar replacement is Stainless Steel, and is Branded Binks
QMGT-5231	83G-221	The regulators on the Similar replacement have a lesser turndown ratio. These are also branded Binks.
<b>5 Gallon</b>		
QMGT-5500	83G-510	The Similar replacement has a single regulator, and is branded Binks.
QMGT-5502	83G-513	The Similar replacement has a single regulator, and an air driven/gear reduced agitator and is branded Binks.
QMGT-5510	83G-510	The Direct replacement is branded Binks. There are no other differences.
QMGT-5512	83G-513	The Similar replacement has a air driven/gear reduced agitator and is branded Binks.
QMGT-5513	83G-513	The Direct replacement is branded Binks. There are no other differences.
QMGT-5520	83G-520	The Direct replacement is branded Binks. There are no other differences.
QMGT-5522	83G-523	The Similar replacement has a air driven/gear reduced agitator and is branded Binks.
QMGT-5523	83G-523	The Direct replacement is branded Binks. There are no other differences.
QMGT-5530	83G-520	The regulators on the Similar replacement have a lesser turndown ratio. These are also branded Binks.
<b>10 Gallon</b>		
QMGT-51000	83G-1010	The Similar replacement has a single regulator, and is branded Binks.
QMGT-51010	83G-1010	The Direct replacement is branded Binks. There are no other differences.
QMGT-51013	83G-1013	The Direct replacement is branded Binks. There are no other differences.
QMGT-51020	83G-1020	The Direct replacement is branded Binks. There are no other differences.
QMGT-51023	83G-1023	The Direct replacement is branded Binks. There are no other differences.
<b>15 Gallon</b>		
QMGT-51500	83G-1500	The Direct replacement is branded Binks. There are no other differences.
QMGT-51510	83G-1510	The Direct replacement is branded Binks. There are no other differences.
QMGT-51513	83G-1513	The Direct replacement is branded Binks. There are no other differences.
QMGT-51520	83G-1520	The Direct replacement is branded Binks. There are no other differences.
QMGT-51523	83G-1523	The Direct replacement is branded Binks. There are no other differences.